TOP SECRET



1 4 DEC 1965

DISTRIBUTION

OS ADMIN SEC BR

P&DS CSD

IPD FD

PSD-ICB

TID

Office Elle

Cy No.

25X1

Acti25X1

25X1

T O P S E C R E T 132223Z

1965 DEC 13 22 37 Z

| PRIORITY | | CITE | 6098 | |
|-----------|---|------|------|--|
| ATTENTION | • | | | |
| | | | | |

SUBJECT: EVALUATION OF MISSION C605C

- 1. CAMERA NUMBER 8 WAS USED IN MISSION C605C FLOWN ON 28 NOVEMBER 1965. PROCESSING WAS ACCOMPLISHED IN THE FIELD.
 - 2. ORIGINAL NEGATIVE:
 - A. EXPOSURE WAS ADEQUATE AND RESOLUTION IS GOOD.
- B. 9R SIDE: EDGE STATIC IS PRESENT ALONG BOTH EDGES OF

 THE FILM. ROLLER CHATTER WAS NOTED ALONG THE INBOARD EDGE.

 EMULSION LIFTS ARE LOCATED IN FRAMES 22 AND 1398. THERE IS A

 TRANSVERSE LIGHT LEAK IN THE FORMAT OF FRAME 54. AN IRREGULAR PLUS Avance copy
 DENSITY STREAK IS PRESENT INTERMITTENTLY THROUGHOUT THE MISSION.

 AN EXAMPLE MAY BE FOUND IN FRAME 1473 OR 2008. HEAT SPLICES ARE

 BETWEEN FRAMES 543/544, 943/944, 1358/1359 AND 1768/1769. MANUFACTUR
 ING SPLICES ARE LOCATED IN FRAMES 1970 AND 2232.
- C. 9L SIDE: MINOR STATIC DISCHARGE TRACES ARE PRESENT
 INFREQUENTLY ON BOTH EDGES. THE INBOARD EDGE CONTAINS INTERMITTENT,
 IRREGULAR PLUS DENSITY STREAKS. A MANUFACTURER'S SPLICE IS POSITIONED INSIDE THE FORMAT OF FRAME 1971.
- D. BOTH SIDES: THE LAST TITLED FRAME OF THE MISSION IS FRAME 2264.
 - E. THERE ARE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

TOP SECRET

- 3. POSITIVE:
 - A. PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING WAS GOOD.
- C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 5 PERCENT OF THE MISSION.

TOPSECRET

:: END OF MESSAGE::